
VALLEY SUB
MAIN –1 West Priority
East Division Terminus MP 45
Santa Maria
W30
WEST
WEST CLINTON SUB
W35
Clinton Diamond
East Solvang Portal
E34
E36
W38
TUNNEL
R1 CLR
M6 CM
R1 CLR
E40
EAST
East Moffat Portal
WEST DIVISION
E45
W40
East Division—Clearance Orders
To West Division
SUMNER SUB
EAST DIVISION
M6 CM
West Division Terminus MP 48
CLINTON SUB
Div. HQ and REA Freight Stub Tracks
W48
M7 WCM
W47
M7
SOLVANG HILL RESORT
WEST CLINTON
E21
R4 FR
R1 CLR
M6 CM
TUNNEL
EAST CLINTON STAGING YARD/ CHICAGO DISTRICT TURNOUT
EAST
W46
WEST
MAIN –1 West Priority
Clinton Station
E23
East Division—Clearance Orders
West Moffat Portal
M6 CM
W44
WEST
TUNNEL
West Solvang Portal
E25
EAST
R1 CLR
SOLVANG SUB
R8
E30
Freight House
Station
Crossing Diamond—West Priority
Reverse Loop Control Block
Manual Switches — Normal to Mains
Control Block Division
R4
E Division Block Marker
M4
W Division Block Marker
E/W6
E or W Division Mile Marker
WEST DIV —RED
EAST DIV —BLUE
CLINTON EAST YARD/ CHICAGO—GREEN
East Bound Traffic must stop for West Bound Traffic at all Crossing Diamonds unless they have Clearance from District Dispatcher to proceed without stopping.